


Условные обозначения



Заливная пробка / Сапун

Пробка контроля уровня

Сливная пробка

C_P



(B5)

_HS


_P (IEC)

_S


B3




W = Default




(C35, C41)




(C35, C41)



(C35, C41)



(C11) (C35, C41) (C21, C31)



C11-C21-C31

2x

2x

3x

C35-C41



C21-C31

3x

4x


C35-C41

B6




W = Default


(C35, C41)




(C35, C41)




(C35, C41)



(C35, C41)



(C35, C41)



C11-C21-C31

2x

2x

3x

C35-C41



C21-C31

3x

4x


C35-C41

B7




W = Default

(C11) (C35, C41)




(C35, C41)




(C21, C31)


(C35, C41)



(C35, C41)



(C11) (C35, C41)



C11-C21-C31

2x

2x

3x


C35-C41

C21-C31

3x

4x

C35-C41



C 11...C 41

C_P



(B6)

_HS

_P (IEC)


_S

B8




W = Default



(C21,C31) (C11,C35,C41)



(C35,C41)



(C35,C41)



C11-C21-C31

2x

2x
3x

C35-C41



C21-C31

3x

4x


C35-C41

V5




W = Default


(C21, C31,C35,C41)



(C35,C41)




(C35,C41)



(C21, C31)



(C35,C41)



C11-C21-C31

2x

2x
3x

C35-C41



C21-C31

3x







4x

C35-C41

V6



W = Default



C11-C21-C31

2x

2x
3x


C35-C41

C21-C31



3x

4x










C35-C41

**C_F****C_U****C_UF**











(B7)

_HS**_P (IEC)****_S****B5**









W = Default


**B51**

W = Default

**B53**

W = Default





C 11...C 41

C_F

C_U

C_UF



(B8)

_HS

_P (IEC)


_S

B52





W = Default


(C21, C31) (C11_U)
(C11_F, C35, C41)




(C21, C31_U) (C21, C31_F)
(C35, C41)



(C35, C41)



(C11_U) (C11_F)
(C21, C31_U) (C21, C31_F, C35, C41)



C11-C21-C31


2x

2x

3x

C35-C41

(C21, C31_F)
(C35, C41)





C21-C31

3x

4x


C35-C41

V1




W = Default


(C21, C31) (C35, C41)




(C11)




(C35, C41)



(C35, C41)



(C21, C31) (C35, C41)



C11-C21-C31


2x

2x

3x

C35-C41

(C11)





C21-C31

3x

4x


C35-C41

V3




W = Default

(C11_F) (C11_F)
(C21, C31_F) (C21, C31_F)
(C35, C41) (C35, C41)




(C21, C31_U)

(C21, C31_F)
(C35, C41)




(C21, C31_U)

(C11_F) (C11_F)
(C21, C31_F) (C21, C31_F)
(C35, C41) (C35, C41)




(C21, C31_U)

(C21, C31_F)
(C35, C41)



(C21, C31_U)

(C11_F) (C11_F)
(C21, C31_F) (C21, C31_F)
(C35, C41) (C35, C41)



(C21, C31_U)


C11-C21-C31

2x

2x

3x

C35-C41




C21-C31

3x

4x

C35-C41



C_P



(B9)

_HS







_P (IEC)

_S

B3





W = Default









2x
3x

4x

B6





W = Default









2x
3x

4x

B7




W = Default



2x
3x

4x



C 51...C 61

C_P



(B10)

_HS






_P (IEC)

_S


B8



W = Default





2x
3x








4x


V5



W = Default










2x
3x




4x


V6



2x
3x



4x



C_F

C_U

C_UF



(B11)

_HS







_P (IEC)

_S



B5











W = Default





B51










W = Default




B53



W = Default





C 51...C 61

C_F

C_U

C_UF



(B12)

_HS






_P (IEC)

_S


B52



W = Default





2x
3x








4x


V1



W = Default





2x
3x








4x


V3




W = Default



2x
3x



4x



C_P



(B13)

_HS







_P (IEC)

_S

B3





W = Default









2x
3x

4x

B6





W = Default









2x
3x

4x

B7




W = Default



2x
3x

4x



C 70...C 100

C_P



(B14)

_HS






_P (IEC)

_S


B8



W = Default





2x
3x








4x


V5



W = Default





2x
3x









4x

V6




W = Default



2x
3x

4x



C_F



(B15)

_HS






_P (IEC)

_S


B5



W = Default





2x
3x








4x


B51



W = Default





2x
3x








4x


B53




W = Default



2x
3x



4x



C 70...C 100

C_F


(B16)

_HS







_P (IEC)

_S

B52





W = Default



2x
3x


4x

V1






W = Default

(C90,C100) (C70,C80)





(P63...P132) (P>132)



2x
3x


4x

V3







W = Default

(C70,C90)
(C100) (C80)



(C70,C80)
(C90,C100)



2x
3x

4x